

Service Bulletins for KGP-560/860 and MK XXI

	Service Bulletin Number	Date	Software /Hardware	Description
6	965-1196-34-06 012-0711-106	Nov 24/04		Updates existing KGP-560 EGPWS PN 965-1196-001 to new PN 965-1198-005
5	965-1198/1199/1227-005-34-05 012-0711-105	Jul 02/04	SW -005 Mod 1	Updates KGP-560 PN 965-1198-005, KGP-860 PN 965-1199-005 and MK XXI PN 965-1227-005 to -005 Mod 1
4	965-1196/11988/1199/1227-34-04 012-0711-104	Jul 02/04	-1196 Mod 3 -1198 Mod 3 -1227 Mod 3 -1199 Mod 1	Allows the latest version of compact flash cards to be used to load software and terrain databases
3	965-1198/1227-34-03 012-0711-103	May 28/04	SW -005	Updates KGP-560 PN 965-1198-003 and MK XXI PN 965-1227-003 to -005
2	965-1196/1198/1227-34-02 012-0711-102	Feb 13/04	-1196 Mod 2 -1198 Mod 2 -1227 Mod 2	Eliminates unnecessary BIT watchdog time-out failures and related computer fail during power-up
1	965-1196/1198/1227-003-34-01 012-0711-101	Apr 16/02	-1196 Mod 1 -1198 Mod 1 -1227 Mod 1	Corrects potential INOP condition at low temperatures